



Large Display Digital Thermometer & Hygrometer

FEATURES

- Measures indoor/outdoor temperature & indoor humidity.
- Stores the Min./Max. values of the indoor/outdoor temperature and indoor humidity.
- Switch between °C and °F.
- 12/24 hour mode switch
- Recovery function on the Min./Max. values.

TECHNICAL PARAMETERS

- Indoor temperature measuring range: -22°F~-122°F (-30°C~+50°C).
- Outdoor temperature measuring range: -58°F~158°F (-50°C~+70°C).
- Indoor humidity measuring range: 20%~99% (relative humidity).
- Resolution: Temperature: 0.1°C; Humidity: 1% RH.
- Power supply: one AAA alkaline battery.
- Operation environment: Temperature: 0°C~50°C; Humidity: 5%~85% RH

OPERATING INSTRUCTIONS

- Automatically memorize the Min./Max. values of indoor/outdoor temperature & indoor humidity.
- Press IN/OUT key to switch between indoor/outdoor temperatures.
- Press MAX/UP key to display memorized indoor/outdoor max temperature and indoor max humidity.
- Press MIN/DOWN key to display memorized indoor/outdoor min temperature & indoor min humidity.
- Press RESET to clear memorized value & start to memorize new max/min value.
- Press 12/24 to switch the time displaying modes.
- Switch °C / °F to display Celsius or Fahrenheit.
- Clock set:
Press Mode key for 3 seconds into time setting mode. When "hour" blinks, press MAX/UP key and MIN/DOWN key to increase or decrease the "hour" value. Holding the key down changes the "hour" value faster. Press Mode key again to confirm, and then "min" blinks, press MAX/UP key and MIN/DOWN key to increase or decrease the "min" value, press Mode key to exit setup of clock.

