Material Safety Data Sheet

Section 1: Company and Product Information

Product Identification

Name: Conductivity Standard Solution as NaCl Code No: 2242-2HM to 224215HM

WET International, Inc. 316 Roma Jean Pkwy. Streamwood, IL 60107 Tel: 630-540-2113

Emergency Response #: 800-535-5053 Infotrac

Section 2: Composition/Information on Ingredients

Hazardous Ingredients

Name	CAS#	%	PEL	TLV	SARA Title 313
Sodium chloride	7647-14-5	<3	None established	None established	No

Non-Hazardous Ingredients

Name	CAS#	%
Water	7732-18-5	>97

Section 3: Physical and Chemical/ Reactivity Properties

Section evil hysical and entiment fledetivity floperties	
Appearance: Clear liquid colorless	Stability: X Stable Unstable
Odor: None	Boiling Point: 212 F/ 100C
pH: 7	Melting Point: N/A
Solubility in Water: Miscible	Vapor Pressure: Same as water
Conditions to Avoid: Extreme temperatures	Hazardous Decomposition Products: None

Section 4: Fire and Explosion Data:

Flash Point: N/A Flammable Limits: LEL: N/A UEL: N/A				
Extinguishing Media: Dry chemicals, CO2 or water spray				
Special Fire Fighting Procedures: Firefighters must wear SCBA				
Unusual Fire or Explosion Hazards: None				
HMIS Hazard: Health: 0 Flammability: 0 Reactivity: 0	Scale: 4=Extreme, 3:	=High, 2=Moderate, 1=	Slight, 0=Least	

Section 5: Health Hazard Data

Toxicity: Acute: irritation to eyes, high blood pressure if taken internally Chronic: No studies performed. Circulatory system is likely to be affected								
Primary Route of Entry:	_Inhalation	X Ingestion	X Skin	Carcinogenicity	X None	_OSHA	_NFT	_IARC
Target Organs:	NIA							
Over Exposure:	See chronic to	oxicity						

Section 6: Emergency First Aid Procedures:

Eye Contact:	Flush with flooding amounts of water. Gently lift the eyelids to rinse. Call for professional medical help
Ingestion:	Contact the poison control center or call 911. Never give anything by mouth to an unconscious or convulsing person.
Inhalation:	Remove exposed person to fresh air and support breathing as needed
Skin Contact:	Flush with flooding amounts of water for at least 15 minutes. Remove contaminated clothing
Others:	After first aid, get appropriate in-plant, paramedic or community medical support.

Section 7: Accidental Release Measures:

Spill/Leak Procedures:	Notify safety personnel, isolate and ventilate the area, deny entry. Shut off ignition sources. Clean up personnel should protect against			
	vapors inhalation and skin/ eye contact			
Small Spills:	Take up with earth, sand, vermiculite or other absorbent non-combustible material and place in suitable containers			
Large Spills:	Containment – Dike far ahead of liquid, semi-solid or solid spills. Do not release into the sewer waterways			
	Regulatory Requirements - Follow applicable OSHA regulations (29 CFR 1910.120) Contact local authorities			

Section 8: Handling and Storage Measures

Section of Handing und	Diving Hemoures
Handling Precautions:	Use gloves, laboratory coats or aprons. Safety glasses should be worn at all times
Ventilation:	Use and storage under proper ventilated areas. Enclosed areas might lead to accumulation of vapors. Mechanical ventilation is
	optimum
Storage Requirements:	Store in cool, dry, well ventilated areas. Avoid excessive heat
Others:	Good working hygiene practices should be observed for personal protection

Disclaimer: The above information is believed to be correct but it does not claim to be all-inclusive and should be used only as guide. Judgements as to the suitability of the information herein for the purchaser's purposes are necessarily the purchaser's responsibility.

Revision Date: May 2007